

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 1 1 3	DATE	M a r . 0 5 . 2 0 1 3
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the drum type braking system, due to an inappropriate manufacturing of brake shoes, an adhesion of the brake shoe and the lining may not be sufficient. For that reason, when repeating the braking operation, the lining may come off and the peeling may be caught in the gap between the drum and the brake shoe causing more than intended braking force that may be put on when braking. Therefore, when running at a low speed, it may face the risk of impairing the running stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B H - S A 3 9 J	J O G C E 5 0 D	2 0 1 1	3, 8 6 2
	J O G C E 5 0 Z R	2 0 1 1	4, 0 0 2
J B H - S A 3 7 J	V i n o X C 5 0	2 0 1 1	1, 2 3 2
	V i n o X C 5 0 D	2 0 1 1	6, 1 9 2
	V i n o M o l f e X C 5 0 H	2 0 1 1	8 4 0
		TOTAL	1 6, 1 2 8