

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3118	DATE	March 5,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the electrical vacuum pump which supplies the negative pressure to the brake booster, the machining oil may have been remained due to the insufficient cleaning of the ring (the cylinder in which the vane is rotating) inside the pump. If use continues under this condition, the vane would be stuck by the oil distilled from the ring causing the vacuum pump to be inoperable which could result in the increase of the stopping distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	「i-MiEV」	2010	2
		2012	281
ZAB-U67V	「MINICAB -MiEV」	2011 TO 2012	70
ZAB-U68V		2013	33
ZAB-U68T		2013	76
		TOTAL	462