

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3116	DATE	March 7 ,2013
MANUFACTURER	ISUZU BODY CORPORATION		
DESCRIPTION OF DEFECT	In vehicles newly equipped with an air tank for the wheel parking brake, note that driving on a bad road with improper clearance between the air tank's drain cock and the propeller shaft may result in interference. This could damage the air tank's drain cock, and possibly result in an air leak. In the worst-case scenario, the wheel parking brake could be activated, thereby keeping the vehicle stationary and unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FRR35G3S	"FORWARD"	2003	1
KK-FRR33E4S		2003	1
KK-FRR33D4V		2003	1
PB-FRR35D3		2004	2
PB-FRR35G3S		2005	1
ADG-FRR90G3S		2006	2
PB-FRR35D3S "kai"(modified)		2006	1
PA-FSR34G4Z		2007	3
PDG-FTR34S2		2007-2010	7
PKG-FSR90S2		2008-2011	6
PKG-FSR34S2		2008	1
PKG-FRR90S2		2008	1
SKG-FSR90S2		2011	1
SKG-FRR90S2		2011	1
LKG-FTR90S2		2012	1
		TOTAL	30

\_\_\_\_\_