

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3117	DATE	Mar.15 2013
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the steering pump, found it has been assembled without the necessary collar between the pump and another one, therefore it may cause an error of the alignment of those drive shafts. Accordingly, when you keep it driving it may become worse of wear for the coupling, then eventually, it may not be possible to steer the vehicle with hydraulic power assistance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-KRC005	KR-25H	2013	1
JDS-KRC007	KRM-25H	2013	1
		TOTAL	2