

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3121	DATE	March 15,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>In the front wheel speed sensor of the affected vehicles, the water may penetrate inside the sensor due to insufficient waterproof performance in the harness of the sensor.</p> <p>If the water penetrates inside the sensor, the output signal from the sensor would be abnormal. As a result, the ABS warning lamp illumination, the needle deflection in the speedometer, the noise by the ABS false activation and/or the vehicle shaking by the TCL false activation would occur, and in the worst case scenario, the braking force could reduce and/or the vehicle could move sideway at the time of sudden braking from high speed.</p> <p>TCL : Traction Control</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-A05A	「MIRAGE」	2012 TO 2013	19,647
		TOTAL	19,647