

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3129	DATE	March. 28, 2013
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Since the engine harness may have been improperly routed during installation process, part of harness may possibly interfere with intake manifold installation bolt during usage. Under these circumstances, improper idling, MIL illumination, etc. may occur if the vehicle was driven continuously. In the worst case, engine will stall and may not be able to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJ2	「IMPREZA」	2012	373
DBA-GJ3			293
DBA-GJ6			424
DBA-GJ7			993
DBA-GP2			1,416
DBA-GP3			653
DBA-GP6			948
DBA-GP7			1,848
DBA-SHJ	「FORESTER」	2012	2,970
DBA-BMM	「LEGACY」	2013	12
DBA-BRM			23
		TOTAL	9,953