

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3130	DATE	March 28 ,2013
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Due to inappropriate shape of cushioning rubber of a fuel tank used on the route bus, in some cases, excessive stress occurs at the fuel tank end when fuel tank bands are tightened. If the fuel tank is used with that condition, crack occurs on the fuel tank by vibration from running vehicle, and for the worst case, fuel leakage might occur.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	[ERGA]	2005-2007	30
PKG-LV234L2		2009	1
PJ-LV234N1		2005-2007	36
PDG-LV234N2		2007-2008	14
PKG-LV234N2			
KL-LV280L1		2001-2005	39
KL-LV280N1		2001-2005	28
		TOTAL	148