

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3131	DATE	Mar.28.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	Due to inappropriate shape of cushioning rubber of a fuel tank used on the route bus, in some cases, excessive stress occurs at the fuel tank end when fuel tank bands are tightened. If the fuel tank is used with that condition, crack occurs on the fuel tank by vibration from running vehicle, and for the worst case, fuel leakage might occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	[HINO Blue Ribbon II]	2007	5
PJ-KV234N1		2007	56
PDG-KV234L2		2007~2008	18
PKG-KV234L2			
PKG-KV234N2		2007~2010	17
		TOTAL	96