

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3132	DATE	March 28 ,2013
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Inappropriate bending was found in the door engine bracket manufacturing process for some of the glide slide doors used on the route bus. This leads to crack on the bracket end, and if the door is used with that condition, the bracket will be broken. For the worst case, it might become impossible to open/close the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	[ERGA]	2004-2007	723
PDG-LV234L2 PKG-LV234L2		2007-2010	774
PJ-LV234N1		2004-2007	277
PDG-LV234N2 PKG-LV234N2		2007-2010	364
KL-LV280L1		2000-2005	591
KL-LV280N1		2000-2005	138
KL-LV280Q1		2001	4
KL-LV834L1		2000-2005	219
KL-LV834N1		2000-2004	45
KK-LR233J1		「ERGA MIO」 「GALA MIO」	1999-2003
KL-KV280L1	「HINO BLUE RIBBON II」	2004-2005	41
KL-KV280N1		2004	4
		TOTAL	3,213