

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3133	DATE	Mar.28.2013
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	Inappropriate bending was found in the door engine bracket manufacturing process for some of the glide slide doors used on the route bus. This leads to crack on the bracket end, and if the door is used with that condition, the bracket will be broken. For the worst case, it might become impossible to open/close the door.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	[HINO Blue Ribbon II]	2004~2007	417
PJ-KV234N1		2005~2007	235
PDG-KV234L2		2007~2010	410
PKG-KV234L2			
PDG-KV234N2		2007~2010	325
PKG-KV234N2			
		TOTAL	1,387