

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 1 5 8	DATE	May.23.2005
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate tightening of the fixing bolt to securing the steering wheel to the steering column, the fixing bolt may loosen and steering wheel play may appear at the serration through the long-term driving. If the vehicle continues to be driven in this condition, the serration will wear and the play grows big, in an extreme case, the vehicle may get out of control with the steering wheel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-AK12	MARCH	2002~2004	138,534
UA-BK12 CBA-BK12			30,786
UA-BNK12 CBA-BNK12			12,875
UA-K12			3,702
UA-BZ11	CUBE	2002~2003	68,161
UA-BNZ11			9,884
		TOTAL	263,942