

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3152	DATE	May 24, 2013
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	On the aerial work platforms, the positions of the rear light assembly, which were re-located at the time of upper-structure-mounting, are incorrect and the positions of the rear reflectors do not comply with the criteria prescribed in the safety standards for Road Trucking Vehicle that specify that the distance between the edge of the rear reflector and the outermost edge of the vehicle shall be 400 mm or less.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-XZU330	DAINA	2001 — 2003	2
KK-XZU340		2003	2
PB-XZU344		2005	1
KK-XZU330M	HINO DUTRO	2002 — 2003	8
KK-XZU340M		2003 — 2004	34
PB-XZU334M		2004 — 2006	8
PB-XZU344M		2004 — 2005	61
BDG-XZU334M		2007 — 2011	28
		TOTAL	144