VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3159	DATE	May 30 ,2013
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The Stabilinker, which is connecting the rear axle to the frame of the air suspension-equipped truck, is not strong enough. For this reason, if the truck repeatedly makes quick turns, the arm of the Stabilinker will be cracked. And if the truck is kept in use, the crack will develop and in the worst case, the arm will be broken and the running performance of the truck will become unstable.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
KL-FSD33T4	[FORWARD]	2002-2004	2
KL-FSD34T4 PJ-FSD34T4		2000-2007	160
PDG-FTR34T2 LDG-FTR34T2 LKG-FTR34T2 QKG-FTR34T2		2007-2012	189
LKG-FTR90T2		2010-2012	32
		TOTAL	383