

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3156	DATE	2013/6/27
MANUFACTURER	THINKTOGETHER, Inc.		
DESCRIPTION OF DEFECT	On the In-Wheel-Motor gearbox, it has been found that over stress may be produced at the hub spindle during operating due to an improper shape and lack of durability. Therefore, when continued being used, the stress will cause the cracks on the hub spindle and in the worst case, the breakage of the hub spindle itself, and finally the wheel will fall off.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
Composition	-	2012	2
		TOTAL	2