

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1942	DATE	27 <sup>th</sup> June 2013
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Japan K.K. )		
DESCRIPTION OF DEFECT	The four bolts that secure the two cable guides located on either side of the mainframe headstock (steering head) contain no patchlock. A risk has been identified where a bolt(s) could therefore loosen. The bolt can become loose which can cause restricted steering movement.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LX	Street Triple	2013	53
		TOTAL	53