## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3162	DATE	Jun 7, 2013
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	get a corrosion the improper combination w leakage of cool air-conditioner case the co- insufficient lub	pore starting from production movith some comprant and lubrical becomes ineffer mpressor shall	at could cause engine

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MK21S	PALETTE	2008	39,873
CBA-MK21S	PALETTE	2008	28,980
DBA-MH23S	WA CON D	2008	12,519
CBA-MH23S	WAGON R	2008	2,930
DBA-MJ23S	AZ WACON	2008	1,923
CBA-MJ23S	AZ-WAGON	2008	63
		TOTAL	86,288