

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3177	DATE	Jun 20, 2013
MANUFACTURER	UD Trucks Corporation.		
DESCRIPTION OF DEFECT	On some route buses with ISS(Idling Stop System), the material of a rubber part used in the starter is improper and the margin for wear of the flywheel ring gear is insufficient. Because of these causes, if the engine is started frequently by the idling stop and start system, the ring gear may wear prematurely. If the vehicle continues to be used in this condition, the starter gear will start to slip and, in the worst case, it will become impossible to start the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-JP820 series	「SPACE RUNNER」	2008	40
PDG-RM820 series	「SPACE RUNNER」	2008	133
PDG-AJ820 series	「FUSO AERO MIDI-S」	2008	15
PDG-AR820 series	「FUSO AERO MIDI-S」	2008	100
		TOTAL	288