

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3181	DATE	Jun/19/2013
MANUFACTURER	Iwasaki Kogyo Corporation		
DESCRIPTION OF DEFECT	<p>In the yellow rotary lamp on a road maintenance vehicle, the inside surface of the main gear used to rotate the reflecting mirror is machined improperly. As a result, when the ambient temperature is low, the inside diameter contracts and the clearance to the bulb socket boss is eliminated in some cases.</p> <p>Therefore, if the lamp is used as it is, the main gear and reflecting mirror may stop, or the lamp may not flash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRS90S2	「FORWARD」	2012	5
SKG-FSS90S2	「FORWARD」	2012	1
		TOTAL	6