

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3179	DATE	19 June 2013
MANUFACTURER	Hitachi Construction Machinery Co. Ltd.		
DESCRIPTION OF DEFECT	<p>Inside the yellow rotary lamp for the road maintenance vehicle, the inside surface of the main gear used to rotate the reflecting mirror is improperly machined. As a result, at a low ambient temperature, the inside diameter of the main gear surface occasionally contacts and causes a gap between the bulb socket boss.</p> <p>This condition may result in the main gear and reflecting mirror rotation to stop, or causing the lamp to not flash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-HS61	「ZW140」	2012	1
		TOTAL	1