## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

$\bigcirc$	omest	ic V	ehi	icles

CAMPAIGN No.	3178	DATE	June 19, 2013		
MANUFACTURER	KCM Corporation				
DESCRIPTION OF DEFECT	Inside the yellow rotary lamp for the road maintenance vehicle, the inside surface of the main gear used to rotate the reflecting mirror is improperly machined. As a result, at a low ambient temperature, the inside diameter of the main gear surface occasionally contracts and causes a gap between the bulb socket boss.  This condition may result in the main gear and reflecting mirror rotation to stop, or causing the lamp to not flash.				

TYPE	COMMERCIAL NAME	YE	DDEL EAR ALLED	NUMBER OF VEHICLE
KDP-50C4	「50ZV-2」	2012-2013		6
KDP-RL08	「LK120Z-6」			5
EDR-60C3	「60ZV-2」			2
EDR-RA08	「LK150Z-6」			2
EDR-65J4	「65ZV-2」			17
EDR-RM06	「LK190Z-6」			1
JDS-70C5	「70ZV-2」			18
JDS-80C5	「80ZV-2」			5
JDS-85C5	「85ZV-2」			4
			TOTAL	61