

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3172	DATE	June. 13. 2013
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>With regard to master power (vacuum power assist of braking system), its housing may have been staked at improper positions during the process of manufacture. When the brake pedal is depressed, the master power's vacuum seal can be dislocated and can be thereby disabled from maintaining the vacuum condition in the master power. Should this happen, the stopping distance after applying the brakes could be longer than the driver expected.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-GJ1	「AIRWAVE」	2006	4,579	
		2006	16,219	
DBA-GJ2		2006	823	
		2006	3,671	
DBA-GK1	「MOBILIO SPIKE」	2006	15,436	
DBA-GK2		2006	4,051	
DBA-GB1	「MOBILIO」	2006	1,516	
		2006	6,450	
		2006	11	
		2006	89	
DBA-GB2		2006	1,315	
		2006	29	
CBA-BE1		「Edix」	2006	2,439
ABA-BE2			2006	406

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BE3	「Edix」	2006	3,041
ABA-BE4		2006	541
CBA-RN1	「STREAM」	2006	4,283
		2006	14
ABA-RN2		2006	639
		2006	4
CBA-RN3		2006	984
		2006	5
ABA-RN4		2006	366
		2006	3
CBA-RN5		2006	691
ABA-DC5		「INTEGRA」	2006
ABA-AP2	「S2000」	2006	1,034
		TOTAL	70,415