

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3165	DATE	June 11 ,2013
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the yellow rotary lamp installed on a road maintenance vehicle, the clearance between the inside wall of the main gear used to rotate the reflecting mirror and the bulb socket boss may be eliminated because of the manufacture dispersion of the main gear when the main gear contracts thermally at low temperature. In this case, the main gear and reflecting mirror do not rotate, and accordingly the lamp does not flash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-WA115	「WA100-6」	2012~2013	78
KDP-WA115	「WA150-6」	2012	21
EDR-WA105	「WA200-6」	2012~2013	28
EDR-WA103	「WA270-6」	2012	3
EDR-WA108	「WA320-6」	2012	3
JDS-WA095	「WA380-6」	2012	1
SB-W108	「WA100-5」	2008~2010	2
		TOTAL	136