

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3171	DATE	Jun 4,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to a slippage solvent applied to the high mount stop lamp affixed to the tail gate, the crack may occur in the nail portion of the high mount stop lamp. If use continues under this condition, the high mount stop lamp could be misaligned from the mounting position on the tail gate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B11W	「eK」	2013	1,449
DBA-B21W	「DAYZ」	2013	7
		TOTAL	1,456