

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3161	DATE	June 4, 2013
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	On the aerial work platforms, the positions of the rear light assembly, which were re-located at the time of upper-structure-mounting, may be incorrect and the positions of the rear turn signal lights may not comply with the criteria prescribed in the safety standards for Road Trucking Vehicle that specify that the distance between the edge of the rear turn signal lights and the outermost edge of the vehicle shall be 400 mm or less.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-NKR81N	ELF	2006 - 2007	92
PDG-NKR85YN		2007 - 2011	135
SKG-NKR85YN		2011 - 2013	105
TKG-NKR85N		2012 - 2013	5
		TOTAL	337