## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN NO.	3195	DATE	July 30 ,2013
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the route buses, it has been found that the compressor vane wheel lacked in strength against variations of turbo charger revolution. When the engine is operated repeatedly using high-speed range at the time when the buses are started, the compressor vane wheel may be damaged. If it is used as is, white smoke and output shortage will cause, thereby rendering the buses inoperative.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PA-LR234J1	[ERGA MIO]	2006	1
PJ-LV234L1	[ERGA]	2005-2007	12
PJ-LV234N1		2006-2007	4
PA-KR234J1	[HINO RAINBOW II ]	2005-2006	2
		TOTAL	19