

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3202	DATE	Aug. 1 2013
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>In some large route buses of the HEV model, the clearance between the intake hose and turbocharger is not sufficient, causing the intake hose rubber to harden due to the heat from the turbocharger. If the intake hose continues to be used in this condition, holes may be made in it. This may cause a larger amount of air to be supplied to the engine than is detected by the air flow sensor mounted on the air cleaner, resulting in the failure to meet the emission standard.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-MP37TK	「FUSO AERO STAR」	2012~2014	3
BJG-MP37TM		2012~2014	34
		TOTAL	37