

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 2 0 5	DATE	August 2, 2013
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>On forklift truck which equipped two LPG cylinders, due to incorrect thread size of the fitting of the plumbing coupling part joined two line of LPG fuel, lack of airtightness at thread might be happened. Therefore if a machine is continuously used under its condition, LPG might be leak out from the thread end of fitting.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M162	「FG35N」	2005～2007	8
M164	「FG45」	2008	2
EBT-M251	「FG35N」	2009	1
		TOTAL	11