

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3203	DATE	August 6, 2013
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>Due to improper installation of cable tie to make starter cable stable, the gap between starter cable and muffler cover of UDPC (UD Particulate Cleaning) emission temperature sensor could have chance to become narrower. If stay on operation, the outer corrugate tube interference with muffler cover might cause the melting. In the worst case, the engine cannot be started due to short-circuit of starter cable.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-MK38L TKG-MK38L	Condor	2010-2013	194
SKG-LK38L TKG-LK38L	Condor	2010-2013	16
		TOTAL	210