

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3206	DATE	Aug. 7, 2013
MANUFACTURE	TADANO LTD.		
DESCRIPTION OF DEFECT	Due to inappropriate position adjustment of the headlight low beam in the production process of some rough terrain cranes, there are cases where the angle of low beam light may exceed the standard adjustment scope and may be angled too high. Therefore, there are cases where this condition may interfere with oncoming traffic and not be in conformance with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T007	TADANO, GR-250N-3	2013	23
		TOTAL	23