

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3207	DATE	August 8,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>Since the manufacturing process of the circuit element which monitors the microcomputer supply voltage in the electrical power steering control unit (EPS ECU) is inappropriate, the characteristics of the element may have been improper. As a result, the supply voltage monitoring circuit may function erroneously and the warning message of “power steering system check” would be displayed on the information monitor, and the steering assist function of the EPS would stop working resulting in the increase of the steering effort.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GF7W	「OUTLANDER」	2012	3
DBA-GF8W		2013	1
		TOTAL	4