

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3208	DATE	August 22 ,2013
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		Regarding vehicles for which Hill Start Aids (HSAs) have been relocated, the exhaust hose of the HSA may come into contact with bolts due to the inadequate mounting position of the HAS, resulting in deformation of the exhaust hose. When a vehicle is driven with such a deformed exhaust hose, it is difficult to effectively discharge the exhaust air when the HAS is released. As a result, brake dragging may occur until the exhaust air is completely discharged.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYZ77AM	"GIGA"	2010-2012	5
LKG-CYZ77AJ		2011	2
QKG-CYZ77AJ		2012	1
LKG-CYM77AM		2011	1
QKG-CYZ77AM		2012-2013	5
		TOTAL	14