

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	3229	DATE	Sep 20,2013
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	Engine flywheel and transmission are connected by a adapter and connection bolts. Since the bolt seating surface of the adapter is not smooth, sufficient fastening power for the bolt is decreased. Therefore, the bolt loosens by vibration in running and the stress added to the bolt increases. If it continues using the vehicle, bolts will be broken and cannot fix the adapter and the vehicle cannot move because the vehicle becomes impossible to transmit power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-2GC	「MITSUBISHI MOTOR GRADER」	2009~2013	341
		TOTAL	341