

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3223	DATE	September 12, 2013
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the directional solenoids of some hydrostatic transmissions, the wirings were installed tense because of improper fixing of them. Accordingly, one of those solenoids is used as it is, its wiring may be broken and the machine may not be able to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-WA105	「WA200-6」	2010-2012	233
		TOTAL	233