

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3221	DATE	September 11, 2013
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In engine crankshaft angle sensor on vehicle, the coil wire may break from excessive vibration when repeatedly driving at high engine revolution, for example, driving at full throttle with low gear position.</p> <p>Therefore, engine may stall while driving or may not start up.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-L235S	ESSE	2005-2010	136,762	
CBA-L245S			16,265	
DBA-L175S	MOVE	2006-2010	161,261	
DBA-L185S			30,831	
DBA-L275S	Mira		77,677	
GBD-L275V			29,110	
HBD-L275V				
DBA-L285S			12,157	
GBD-L285V			3,944	
DBA-L375S			TANTO	2007-2010
CBA-L385S	28,343			
CBA-L465S	TANTO Exe		2009	6
DBA-L575S	MOVE Conte	2008-2009	14,416	
DBA-L585S			2,484	
DBA-L675S	Mira Cocoa	2009	1,389	
DBA-L685S			254	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S201C	HIJET	2007-2010	796
EBD-S201P			37,698
EBD-S321V			65,450
GBD-S321V			
EBD-S211C			201
EBD-S211P			84,671
EBD-S331V			31,862
GBD-S331V			
EBD-S321W	HIJET DECKVAN	2007-2009	1,091
EBD-S331W			1,468
ABA-S321G	ATRAI WAGON	2007-2010	28,119
ABA-S331G			11,129
ABA-S321N	DIAS	2009	319
ABA-S331N			242
		TOTAL	891,525