

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3198	DATE	July 25,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the Exhaust Gas Recirculation (EGR) of the affected vehicles, due to inappropriate sealing mechanism of the bush located on the valve shaft, the sealing performance may be decreased when the valve shaft is in operation causing the exhaust gas to be intruded into the motor. After that, if the conduction failure occurs due to the abnormal abrasion of the brush inside the motor, the EGR valve function may stop resulting in the illumination of the engine warning lamp.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADC-V88W	「Pajero」	2009～2010	170
ADC-V98W		2008～2010	1,741
LDA-V88W		2010～2011	271
LDA-V98W		2010～2011	2,029
		TOTAL	4,211