

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 1 9 0	DATE	July.18.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to inappropriate operation instruction for the installation of the vacuum hose, the vacuum hose may interfere with the engine cover. If the vehicle continues to be driven in this condition, the vacuum hose may be made a hole, and the brake performance may deteriorate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-TB17	SYLPHY	2 0 1 2 ~ 2 0 1 3	9, 2 1 4
		TOTAL	9, 2 1 4