

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3189	DATE	July 17,2013
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing process in the locking mechanism of the retractor for the front seatbelt system, the pressed portion may be loosened causing abnormal noise or the belt to be caught when the seatbelt is fastened or released. Use continues under the condition, in the worst case, the pressed part may be removed and the locking mechanism may not operate properly when the vehicle is in crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GBD-U61V	「MINICAB」	2012~2013	5,677
EBD-U61V		2012~2013	254
GBD-U62V		2012~2013	3,709
EBD-U62V		2012~2013	329
ZAB-U67V	「MINICAB -MiEV」	2012	99
ZAB-U68V		2013	72
GBD-U71V	「CLIPPER」	2012~2013	9,125
EBD-U71V		2012~2013	470
GBD-U72V		2012~2013	3,611
EBD-U72V		2012~2013	312
		TOTAL	23,658