

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

**Domestic Import Vehicles**

CAMPAIGN NO.	3251	DATE	October 31 ,2013
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Some drive pinions for differential gears have a machining defect in their bearing inner ring raceway surface. Continued use could lead to the bearing being damaged, and could lead to oil leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-CYH77A	[GIGA]	2012	1
KL-CYJ51W3		2000	1
QKG-CYJ77A OKG-CYJ77AA		2012	7
QKG-CYY77AY		2012	5
QKG-CYZ77AJ		2012	2
SKG-FRR90S1 SKG-FRR90S2 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2012	40
SDG-FRS90S1		2012	1
SKG-FSR90S2 SKG-FSR90T2		2012	17
QKG-FTR34S2 OKG-FTR34T2		2012	5
LKG-FTR90S2 LKG-FTR90T2		2012	7
KC-LR33J	[JOURNEY K]	1999	1
TKG-NKR85N TKG-NKR85R	[ELF]	2012	7
SKG-NKR85YN		2012	2
TKG-NMR85N TKG-NMR85R		2012	7
TKG-NPR85AN TKG-NPR85AR TQG-NPR85AN		2012	58
SKG-NPR85YN		2012	33
TDG-NPS85AN TDG-NPS85AR		2012	10

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-AMR85N	[ATLAS]	2012	2
TKG-APR85AN		2012	4
SKG-APR85YN		2012	2
TKG-LPR85AR	[TITAN]	2012	1
SKG-LPR85YN		2012	1
		TOTAL	214