

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 4 8	DATE	Oct.31.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate the shape of the cover for the high pressure fuel pump, the moisture content in the fuel may freeze during continuous driving under the extremely low temperature and the grains of ice may accumulate in the filter area of the high pressure fuel pump. As a result, the warning lamp will be turned on and the engine may become out of condition. In an extreme case, the engine may stall.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-FC26	SERENA	2010 ~ 2013	83,041
DBA-FNC26			18,081
DBA-C26			50,035
DBA-NC26			12,838
DAA-HFC26			62,475
DAA-HC26			25,387
DBA-SC26			SUZUKI LANDY
DBA-SNC26	811		
DAA-SHC26	948		
		TOTAL	256,519