

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3256	DATE	October 30, 2013
MANUFACTURER	Mitsuoka Motor Co., Ltd.		
DESCRIPTION OF DEFECT	<p>① Because the strength of the steering device (front fork) is low, when I input the big impact strength to the front wheel by the run of the step of a bad road and the road surface repeatedly, the front fork transforms it when it is the worst, and operation performance and the stability of the vehicle might decrease.</p> <p>② When cover water does a large quantity of rainwater including the torrential rain, water may invade to the electric point of contact part in the switch because the waterproofness of the Horn switch is inappropriate. Therefore Horn might rumble regardless of the operation of the Horn switch.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAE-MT3	Like-T3	2012~2013	9
TOTAL			9