

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3249	DATE	30 October 2013
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO. , LTD		
DESCRIPTION OF DEFECT	In the term of use of travel pump that is mounted on our shovel loader, the pins which are supporting the bearing retainer in the travel pump may wear. If it is used continually, the pins may break. If these pins break, bearing retainer is not supported. If it is the worst that there is possibility the bearing will break and the travel pump will work abnormally then it will not able to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-HS59	「ZW100」	2010 - 2012	829
KDP-HS59L		2011 - 2012	7
KDP-HS60	「ZW120」	2010 - 2012	87
KDP-HS60L		2010 - 2012	6
KDP-S59	「ZW100」	2010 - 2011	93
KDP-S60	「ZW120」	2010	20
EDR-HS61	「ZW140」	2007 - 2012	212
EDR-HS61L		2011 - 2012	3
EDR-HS62	「ZW150」	2008 - 2012	31
EDR-S61	「ZW140」	2007 - 2010	100
EDR-S62	「ZW150」	2008 - 2010	28
		TOTAL	1,416