VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicle

		Ĩ	-			
CAMPAIGN No.	3239	DATE	October 24,2013			
MANUFACTURER	Kobelco Cranes Co., Ltd.					
DESCRIPTION OF	DEFECT-1 (D-1)					
DEFECT	It was found that the headlights of wheeled mobile crane might					
	be malfunction due to blowing of fuse. This might be happened					
	when the headlight module contacts to its mounting frame					
	abnormally and electric short-circuit occurs.					
	DEFECT-2 (D-2)					
	As wheeled mobile crane, there are several steering modes					
	provided for traveling in off-road, and it was found malfunction					
	on its steering modes as the mode might not be changed even					
	right operation provided due to the stuck of selector spool in hydraulic valve caused by contamination in hydraulic line.					

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
IIPE	NAME	RECALLED		VEHICLE
JDS-EE02	RK250-7	2008 to 2013		292 units
				(D-1:88 / D-2:292)
UDS-EE04 RK250-8		2013		15 units
			(D-1:14 / D-2:15)	
JDS-EG02	RK700	2009 to 2013		57 units
				(D-1:16 / D-2:57)
			TOTAL	364