

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-1972	Date	October, 24, 2013
Manufacturer	Jaguar Land Rover Limited (Japanese Importer: Jaguar Land Rover Japan Limited)		
Description of defect	<p>A concern has been identified with certain X-Type 2001.25 to 2008 MY and S-Type 2002.5 to 2008 MY vehicles in Japan where the High Intensity Discharge (HID) headlamps fail to operate after recall Gai-1809 (J021) has been performed.</p> <p>Certain headlamps changed as part of Recall Gai-1809 (J021) may have HID ballast modules within the headlamps that could fail due to Electro Static Discharge (ESD) damage.</p> <p>ESD event could cause the dipped beam function within the headlamp assembly to fail, this could cause one headlamp, or in extreme circumstances both headlamps to lose the dipped beam lighting function however, the main beam lighting function remains operational.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
GH-J51YA	「X-TYPE 2.0 V6」	2001.25 - 2008	111
ABA-J51YB	「X-TYPE 2.0 V6 Estate」		159
GH-J51XA	「X-TYPE 2.5 V6」 「X-TYPE 2.5 V6 SE」	2001.25 - 2008	218
ABA-J51XB	「X-TYPE 2.5 V6 Sport」 「X-TYPE 2.5 V6 Estate」		450
GH-J51WA	「X-TYPE 3.0 V6 SE」	2001.25 - 2008	96
ABA-J51WB	「X-TYPE 3.0 V6 SE」 「X-TYPE 3.0 V6 Sport」 「X-TYPE 3.0 V6 Sovereign」		88
GH-J01JC	「S-TYPE 2.5 V6」	2002.5 - 2008	455
GH-J01FC	「S-TYPE 3.0 V6」	2002.5 - 2008	778
CBA-J01FD			506
GH-J01HC	「S-TYPE 4.2 V8」	2002.5 - 2008	158
CBA-J01HD			53
GH-J011C	「S-TYPE R」	2002.5 - 2008	203
CBA-J011D			30
		Total	3,305

(JIS A4 size)