

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3241	DATE	October 10.2013
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	Brake may not perform enough due to improper placement of oil return pipe connected from the brake valve tank, which will allow the air to be taken into the pipe.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-105B	「 EG97 」	2011~2013	69
	「 EG105 」	2011~2013	332
TOTAL			401