## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3235	DATE	October.4.2013		
MANUFACTURER	Niigata Transys co.ltd.				
DESCRIPTION OF DEFECT	drive the vehic	There is a possibility that it becomes impossible to drive the vehicle, by oil leaking from the hydraulic pump attached the screw incorrectly in the engine room.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
JDS-NR6A	NR282	2009/2010		13
JDS-NR6A	NRN282	2009		1
JDS-NR6A	NR301	2009/2010		8
JDS-NR6A	NRN301	2009		1
JDS-NR6A	NRNS302	2010		1
			TOTAL	24