

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 3 3	DATE	Oct.3.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate shape of the die for the selector lever knob, the engagement area for the selector button in the knob might be damaged at the surface molding process of the knob. This can cause the retention force of the selector button to be deteriorated, and the selector button may come out by the impacts at the operation of the shift selector. Therefore, the selector button cannot be pushed occasionally. As a result, the shift selector may be unable to be operated from the P position or to the P and R position.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBF-VY12	NISSAN AD / AD EXPERT	2013	4,162
DBF-BVY12	MAZDA FAMILIA VAN		515
DBF-CVY12	MITSUBISHI LANCER CARGO		229
		TOTAL	4,906