

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN NO.	3 2 5 2	DATE	October ,21,2013
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.LTD.		
DESCRIPTION OF DEFECT	During the production process of engine cooling system on the combine harvester, defective pulley which has low strength bolt sheeting surface was mixed. Due to this defective, pulley may break and cause to stop of cooling fan turning. If the machine is continuously used under this condition, overheating may be occurred due to the deterioration of cooling performance.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-VC63A	「VY463」	2013	9
	「VG653」		5
KDN-VC63B	「HC650」		3
TOTAL			17