

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3234	DATE	September 27 ,2013
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		The sound insulator was improperly installed on the cabin floor of the remodeled double-cabin vehicle. As a result, the sound insulator may droop and touch the EGR cooler due to cooling air while the vehicle is running. The sound insulator in contact with the EGR cooler may be very hot and in extreme cases could even burn out.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-FVR34U2 "kai"(modified)	"FORWARD"	2009-2010	4
PDG-FTS34S2		2008	1
LKG-FVR34U2 "kai"(modified)		2010	3
		TOTAL	8

|