

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 2 6 5	DATE	Nov.28.2013
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to incorrect die was used in the forging process of the armature with the pulley on the air compressor. Therefore the strength of the armature may deteriorate. If the vehicle continues to be driven in this condition, the armature may fall off the compressor and the air conditioner cannot operate. In an extreme case, the armature may fall off on the road.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-SQ2F24	N I S S A N 「ATLAS」	2 0 1 2 ~ 2 0 1 3	998
CBF-SQ1F24			151
SKG-SZ2F24 TKG-SZ2F24			859
SDG-SZ5F24			449
SKG-SZ1F24 TKG-SZ1F24			40
SDG-SZ4F24			19
SKG-TZ2F24			279
SKG-TZ3F24			59
CBF-ASQ2F24	I S U Z U 「ELF」		6
CBF-ASQ1F24			3
SKG-ASZ2F24 TKG-ASZ2F24			12
SDG-ASZ5F24			2
SKG-ASZ1F24			2
CBF-USQ2F24	U D T R U C K S 「CONDOR」	2 0 1 3	1
CBF-USQ1F24			1
SKG-USZ2F24			5
SDG-USZ5F24			8

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
SKG-UTZ2F24	UD TRUCKS 「CONDOR」	2 0 1 3	3
SKG-UTZ3F24			3
SKG-BSZ2F24 TKG-BSZ2F24	MITSUBISHI FUSO 「CANTER」		52
SDG-BSZ5F24			50
SKG-BSZ1F24			12
CBF-SQ2F24	NISSAN 「ATLAS」	2 0 0 1 ～ 2 0 1 1 The vehicles are replaced to the affected parts at the service station.	4
PDG-SZ2F24			7
PDG-SZ4F24			1
PDG-TZ2F24 PKG-TZ2F24			4
KG-VWE25 KR-VWE25 ADF-VWE25	NISSAN 「CARAVAN」		43
KG-VWME25 KR-VWME25			11
CBF-VRE25			21
KG-CWGE25 KR-CWGE25 ADF-CWGE25			8
KG-CWMGE25 KR-CWMGE25			7
CBF-CSGE25			3
CBA-SGE25			6
CBA-SE25			1
CBF-DSGE25			1
KR-DWGE25			2
KR-DWMGE25			1
CBF-JVRE25	I S U Z U 「COMO」		1
KR-JCWMGE25			1
		TOTAL	3, 136