## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3262	DATE	Nov 14, 2013	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Bolts that fasten drive plate and torque converter may become loose and drop off due to insufficient fastening torque on vehicles with Continuously Variable Transmission (CVT) or Automatic Transmission (AT). That leads to abnormal noise and in the worst case, the dropped bolts can be bitten by the drive plate and cylinder block, ending up to possible engine stole and unable engine restart.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZC72S			2,582
DBA-ZD72S	SWIFT	$2012 \sim 2013$	271
CBA-ZC32S			306
DBA-YA11S	SX4	$2012\sim2013$	41
DBA-YB11S			30
DBA-YC11S			7
CBA-RE91S	IZIZ A CILI	2012 ~ 2013	59
CBA-RF91S	KIZASHI		5
		TOTAL	3,301